| Attachment 3: The modes of delivery against the summary in the motorcycle/SBD report<br>Reviewing the OHS consequences of Motorcycle Separate Bundle Delivery         |  |  |  |  |  |
|---|--|--|--|--|--|
| MOTORCYCLE  | BICYCLE  | E-TRIKE  | PUSH BUGGY   | Comments   |  |
| Organisational Issues   |  |  |  |  |  |
| <ol> <li>The proposed work system increases<br/>the likelihood that PDOs will work for<br/>long periods without breaks in an<br/>uncontrolled environment.</li> </ol> | Likely to be the same<br>organisational issues as per<br>the motorcycle. | Likely to be the same<br>organisational issues as per<br>the motorcycle. | Likely to be the same<br>organisational issues as per<br>the motorcycle. | It is assumed that the<br>intended work system will be<br>substantially the same as<br>that used in the SBD trials.<br>The report highlighted many<br>deficiencies in this work<br>system and judged it to be<br>unacceptable.<br>The SBD design process<br>has focused solely on the<br>equipment design and has<br>attempted to make the<br>Separate Bundle Delivery<br>method fit the same work<br>system as for single bundle<br>delivery. |  |

|    | Attachment 3: The modes of delivery against the summary in the motorcycle/SBD report<br>Reviewing the OHS consequences of Motorcycle Separate Bundle Delivery   |  |  |  |   |  |
|----|---|--|--|--|---|--|
|    | MOTORCYCLE  | BICYCLE  | E-TRIKE  | PUSH BUGGY   | Comments  |  |
|    |   |  |  |  |   |  |
| 2. | The cognitive demands are self-<br>evidently increased (over single<br>bundle delivery)<br>-two reading tasks to perform per<br>delivery point<br>-sighting points are separated and<br>may be in different orientations,<br>requiring addresses to be read upside<br>down.<br>-frequency of mis-sorts increases<br>cognitive load. | Likely to be the same<br>organisational issues as per<br>the motorcycle.   | Likely to be the same<br>organisational issues as per<br>the motorcycle.   | Likely to be the same<br>organisational issues as per<br>the motorcycle.   | As above (1).   |  |
| 3. | AP has not identified any adequate<br>risk controls to prevent 'reading and<br>riding' other than administrative<br>controls, enforced by surveillance of<br>the PDOs.  | Likely to be the same<br>organisational issues as per<br>the motorcycle but risks not<br>likely to be as high as speed<br>and other risk variables of<br>vehicle type lower. | Likely to be the same<br>organisational issues as per<br>the motorcycle but risks not<br>likely to be as high as speed<br>and other risk variables of<br>vehicle type lower. | Not applicable.  | Reading and riding has not<br>been adequately defined by<br>AP and is often confused<br>with the glancing that is<br>normal driving behaviour<br>when checking instruments,<br>mirrors, etc.<br>The surveillance of PDOs is<br>impractical as a risk control. |  |
| 4. | No acceptable form of management<br>or work design to prevent PDOs<br>having to perform long spells of<br>continuous delivery work with<br>insufficient breaks in order to meet<br>delivery time requirements.  | Likely to be the same work<br>system as that for<br>motorcycles but with the<br>additional physical loading<br>of propelling the bicycle as<br>well as merging the mail      | Likely to be the same work<br>system as that for<br>motorcycles. The physical<br>demands may be less than<br>the bicycle but more than<br>the motorcycle.                    | Likely to be the same work<br>system as that for<br>motorcycles but the PDO<br>will not be constrained by<br>being seated for the duration<br>of the round (but will have to | Will remain unresolved as<br>long as AP resists efforts to<br>redesign the work system as<br>a whole, rather than the<br>piecemeal approach used at<br>present where the emphasis   |  |

| Attachment 3: The modes of delivery against the summary in the motorcycle/SBD report |  |  |  |  |  |
|--|--|--|--|--|--|
| Reviewing the OHS consequences of Motorcycle Separate Bundle Delivery                |  |  |  |  |  |
| MOTORCYCLE BICYCLE E-TRIKE PUSH BUGGY Comments                                       |  |  |  |  |  |
|  |  |  |  |  |  |

|   |   | (and posting it.)  |  | walk the whole distance).  | is on the equipment issues alone. |
|---|---|--|--|--|-----------------------------------|
| í | <ul> <li>The methods for determining the size,<br/>and therefore the duration, of rounds<br/>do not appear to be adaptable to the<br/>realities of the work demands.</li> <li>Previous recommendation that rounds<br/>be a maximum of five hours in<br/>duration is routinely exceeded.</li> </ul>  | Likely to be the same issues<br>as per the motorcycle.                   | Likely to be the same issues as per the motorcycle.                      | Likely to be the same issues<br>as per the motorcycle.                   | As above (4).                     |
| ( | b. The design of the work system for<br>SBD does not take account<br>contemporary expectations for a<br>compatible work-life balance,<br>particularly when there is<br>inconsistency in what part of<br>the day is occupied by work, and what<br>part of the day is non-work.   | Likely to be the same<br>organisational issues as per<br>the motorcycle. | Likely to be the same<br>organisational issues as per<br>the motorcycle. | Likely to be the same<br>organisational issues as per<br>the motorcycle. | Refer points (1) and (4) above.   |
|   | 7. There does not appear to be a<br>coherent job description for the duties<br>of a PDO engaged in SBD, defining<br>the allowances and requirements for a<br>properly structured shift of work,<br>including the periods of work for each<br>activity, the breaks to be taken, and<br>providing for the work to be performed<br>in well-managed work circumstances. | No information available so<br>mot able to assess.                       | No information available so<br>not able to assess.                       | No information available so<br>mot able to assess.                       | As above.                         |

|    | MOTORCYCLE   | BICYCLE  | E-TRIKE  | PUSH BUGGY  | Comments   |
|----|--|--|--|---|--|
| En | vironmental Issues   |  |  |   |  |
| 1. | Increased exposure peak hour<br>traffic on roads, footpaths and across<br>domestic driveways, in the mornings<br>and, for some, in the afternoons also.  | Much the same hazards but<br>slightly less road exposure<br>(but greater risk when on<br>roads?)   | As for bicycles.   | Not as much of an issue for<br>buggies as these tend to be<br>used in high density areas<br>such as commercial<br>districts.                                |  |
| 2. | Ergonomics analysis indicates that<br>the task involves unacceptable work<br>postures and upper limb actions that<br>are identified as risk factors in the<br><i>National Code of Practice for the</i><br><i>Prevention of Musculoskeletal</i><br><i>Disorders from Performing</i><br><i>Manual Tasks at Work.</i> | Risks documented in the<br>Manual Handling Code<br>assessment document (doc.<br>1). Many risks similar to<br>motorcycle because of<br>equipment layout and<br>working repeatedly to left.  | Many similar hazards and<br>risks as for the bicycle but<br>possibly (slightly) better<br>manual handling depending<br>on how the PDOs access<br>the rear bin. | Risks documented in<br>Manual Handling Code<br>assessment document but<br>generally the buggies are<br>likely to be the less<br>hazardous mode of the four. | Refer document 1.  |
| 3. | The use of motorcycles in mail<br>delivery has an elevated level of<br>hazard particularly when delivering in<br>terrain that is hilly, and on surfaces<br>that are slippery and uneven.   | Likely to be the same issues<br>as for the motorcycle but the<br>bicycle may be worse<br>because there is little power<br>(human strength only) and<br>small tyre contact area. The<br>bicycle may also be top<br>heavy because of the large<br>front carrier. | Similar to be the bicycle.<br>The E-trike may be difficult<br>to control on adverse lateral<br>slopes and could tip over in<br>some circumstances.             | Generally not a problem.<br>While the buggy might be<br>awkward to control in some<br>circumstances it is unlikely<br>to present actual risk to<br>PDOs.    | There does not appear to<br>have been enough<br>clarification of the road-<br>related hazards even thoug<br>the problems are known,<br>particularly for the<br>motorcycles.<br>The accident records for<br>bicycles are not known but<br>cyclists are always at high<br>levels of risk on roads. |

| /  | Attachment 3: The modes of delivery against the summary in the motorcycle/SBD report<br>Reviewing the OHS consequences of Motorcycle Separate Bundle Delivery  |  |   |  |   |  |
|----|--|--|---|--|---|--|
|    | MOTORCYCLE   | BICYCLE  | E-TRIKE   | PUSH BUGGY   | Comments  |  |
| Eq | juipment issues  |  |   |  |   |  |
| 1. | The motorcycles or panniers are not<br>sufficiently adjustable to suit riders<br>and therefore do not accord with basic<br>ergonomics principles for the design<br>of work equipment.  | Likely to be the same issues<br>as per the motorcycle. Front<br>letter container is a potential<br>balance problem and may<br>require extended forward<br>reaching. NB The bicycle<br>has not been examined in<br>detail by the authors. | Similar issues to those of<br>the motorcycle but<br>potentially less hazardous if<br>the rear bin causes the PDO<br>to dismount in order to<br>access it (rather than reach<br>back from the seat). NB.<br>Same caveat as for bicycles. | Would not expect this to be<br>an issue for the buggies but<br>this matter is somewhat<br>unclear as the buggies have<br>not been examined by the<br>authors of this report.         | Despite the emphasis on the<br>design of the front letter<br>carrier for SBD, the<br>equipment design for mail-<br>carrying is not very good.                 |  |
| 2. | The length of time spent on these<br>motorcycles every day is judged to be<br>unacceptable because the lack of<br>adjustment will cause many PDOs to<br>spend long periods in slumped and<br>unsupported sitting while subject to<br>whole body vibration, exacerbated by<br>the weight of the helmet. | Some similar issues to those<br>of the motorcycle. Hand/arm<br>vibration risk still applies due<br>to tight gripping. Cyclists'<br>helmet is much lighter and<br>there has been an option to<br>not wear it (does this still<br>apply?)  | Similar to both motorcycle<br>and bicycle.  | Issue of prolonged<br>unsupported standing and<br>walking with unclear<br>opportunities for rest breaks.<br>The overall physical<br>demands imposed by these<br>buggies are unclear. | This can only be addressed<br>by reviewing the design of<br>the whole system of work,<br>rather than just<br>incrementally changing parts<br>of it at a time. |  |
| 3. | The bundle sizes of 70 mm and 90<br>mm that are required by the design of<br>the FLC are too large for many<br>smaller sizes of hands.   | Likely to be the same issues<br>as per the motorcycle.   | Likely to be the same issues as per the motorcycle.   | Likely to be the same issues as per the motorcycle.  | PDOs self-select smaller<br>bundles which the means<br>there are more bundles.<br>One manual handling<br>problem is exchanged for<br>another.                 |  |
| 4. | While the front letter carrier is simply<br>an adaptation of the previous bag, the<br>compartmental design imposes   | Likely to be the same issues as per the motorcycle.  | Likely to be the same issues as per the motorcycle.   | <ul> <li>Difficult to tell from current<br/>pictorial information –<br/>appears two different</li> </ul>   | Refer comments in (1) and (2) above.  |  |

| Attachment 3: The modes of delivery against the summary in the motorcycle/SBD report |  |  |  |  |  |
|--|--|--|--|--|--|
| Reviewing the OHS consequences of Motorcycle Separate Bundle Delivery                |  |  |  |  |  |
| MOTORCYCLE BICYCLE E-TRIKE PUSH BUGGY Comments                                       |  |  |  |  |  |
|  |  |  |  |  |  |

|    | additional physical demands on the<br>PDOs using it in respect of neck<br>movements and upper limb actions.   |   |   | layouts available. Cannot be<br>clearly assessed as the two<br>buggies have not been<br>sighted by us.   |  |
|----|---|---|---|--|--|
| 5. | The weight of and heat generated by<br>the current helmet combine to<br>undermine the comfort and increase<br>fatigue of PDOs, compounded by the<br>neck posture required for the task. | The cyclists use a lighter<br>helmet which may cause<br>temperature discomfort in<br>some circumstances but is<br>generally not a problem for<br>biomechanical stress to the<br>neck. | The cyclists use a lighter<br>helmet which may cause<br>temperature discomfort in<br>some circumstances but is<br>generally not a problem for<br>biomechanical stress to the<br>neck. | Not an issue for buggy<br>users.   |  |
| 6. | The motorcycle and its attachments<br>are not adequately developed as they<br>should be for this type of work.  | Likely to be the same issues<br>as per the motorcycle.  | Likely to be the same issues<br>as per the motorcycle.  | Need to view the buggy<br>prototypes in action to<br>assess. There are significant<br>differences between the<br>buggies in terms of wheel<br>size and arrangements, and<br>the configuration of the mail<br>carrying and merging. We<br>are not clear whether the<br>buggies are of an adequate<br>standard of design for SBD.<br>The PT200 buggy appears<br>to be a converted shopping<br>trolley. | Refer all points above<br>related to equipment design. |